



Cessna
A Textron Company

PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION 411126 N1133G
PROPELLER MODEL AND SERIAL HC-434F-1RF/F7693DFK LX 580B
HUB SERIAL A 97538B BLADE SERIALS K82340 , K82339 , K82338



INSTRUCTIONS

This record should be completed and maintained in accordance with FAA Federal Aviation Regulations 43.9, 43.11 and 91.417 and/or other prevailing government regulations.

NOTE: Record Service Bulletins and Airworthiness Directives in the back of this record as well as the Airframe Maintenance Record.

Copyright © 1996


MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
12-9-2008	0	0	Hartzell Propeller S/N LX580B installed on engine S/N 804067, aircraft S/N 411126.	 Mike Harder Cessna ODA PC ODA-100129-CE
DATE 2-17-09			HOBBS 19.8 N1133G REPAIRED PROP DE-ICE BOOT CONNECTOR. OPERATIONAL CHECK PERFORMED SATISFACTORY. END.	
			 SELECT AIRCRAFT SERVICE ADP 2421 400971A	

MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			<p>DATE 9-18-09 HOBBS 231.4 TT 231.4 N1133G</p> <p>I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AND AIRWORTHY CONDITION. DRESS OUT PROPELLER. ALL AD'S CURRENT SEE AD LIST. OPERATIONAL AND LEAK CHECK PERFORMED SATISFACTORY. END.</p> <p><i>[Signature]</i> APZ62640097 1A SELECT AIRCRAFT SERVICE</p>	

MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			<div> <div> <p>PROP MODEL: PROP S/N: REG. NO: 1134G WORK ORDER: 8745</p> </div> <div>  <p>Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450</p> </div> <div> <p>DATE: 11/12/2009 A/C TSN: 249.2 PROP TT: HOBBS: 249.2</p> </div> </div> <p>Prop Entries (2) INSTALLED NEW PROP HUB HALF BOLT.</p> <p>The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.</p> <div> <p>DATE: 11/12/2009</p> <p>SIGNED: <i>[Signature]</i> Frank R Galella</p> <p>Work Order: 8745 Printed by EBis 3 (datcomedia.com)</p> </div>	

MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			<p>CHAUTAUQUA AIRCRAFT 3163 AIRPORT DR. BOX 11 JAMESTOWN, NY 14701</p> <p>Phone: 716-664-7700 Fax: 716-664-7714 CRS# IC1R213K</p> <p>Work Order# 7178 Date: 09/22/10 Aircraft: N1133G Prop Serial: LX580B Total Time: 553.3 Complied with Annual Inspection in accordance with 14 CFR 43 appendix D. Re-secured 1 TKS prop boot and applied edge sealer as per TKS Instructions. Checked AD's for compliance thru issue 2010-19. I certify this Propeller has been inspected in accordance with an Annual Inspection and is approved for return to service.</p> <p><i>[Signature]</i> Kerby McCall CRS#IC1R213K W.O.# 7178</p>	



GOODRICH AVIATION MAINTENANCE CENTER

Greater Binghamton Airport 607-821-2982 www.GoodrichAviation.com

Due to the age of the aircraft, the propeller was inspected and found to be in good condition.

DATE 19__	T HC		MAINTENANCE ITEMS PERFORMED:	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
			<p>1. Installed Hartzell HC-H3YF-1RF, S/N LY580B, after cleaning and inspection. See East Coast Propeller Service Yellow Tag dated 5/19/11 and work order ER-8692. Used new C-3317-228 o-ring.</p> <p>2. Installed overhauled propeller governor, P/N C290D3R/T43, S/N 071160. See New England Propeller Service work order CR-38019.</p> <p>Douglas Goodrich <i>[Signature]</i> AP3460684</p>	